

# UCLA

## UCLA Previously Published Works

### Title

*Mycobacterium chimaera* infections among cardiothoracic surgery patients associated with heater-cooler devices-Kansas and California, 2019.

### Permalink

<https://escholarship.org/uc/item/58m7w808>

### Journal

Infection control and hospital epidemiology, 43(10)

### ISSN

0899-823X

### Authors

Xu, Kerui  
Finn, Lauren E  
Geist, Robert L  
et al.

### Publication Date

2022-10-01


### DOI

10.1017/ice.2021.396

Peer reviewed

## Original Article

# *Mycobacterium chimaera* infections among cardiothoracic surgery patients associated with heater-cooler devices—Kansas and California, 2019

Kerui Xu PhD<sup>1,2,a</sup> , Lauren E. Finn MPH<sup>3,a</sup>, Robert L. Geist MPH<sup>4</sup>, Christopher Prestel MD<sup>1</sup>, Heather Moulton-Meissner PhD<sup>1</sup>, Moon Kim MD<sup>3</sup>, Bryna Stacey MPH<sup>4</sup>, Gillian A. McAllister<sup>1</sup>, Paige Gable MPH<sup>1</sup>, Talar Kamali MSN<sup>3</sup>, Annabelle de St Maurice MD<sup>5</sup>, Shangxin Yang PhD<sup>6</sup>, Kiran M. Perkins MD<sup>1</sup> and Matthew B. Crist MD<sup>1</sup>

<sup>1</sup>Division of Healthcare Quality Promotion, Centers for Disease Control and Prevention, Atlanta, Georgia, <sup>2</sup>Epidemic Intelligence Service, Centers for Disease Control and Prevention, Atlanta, Georgia, <sup>3</sup>Los Angeles County Department of Public Health, Los Angeles, California, <sup>4</sup>Kansas Department of Health and Environment, Topeka, Kansas, <sup>5</sup>Department of Pediatrics, Division of Pediatric Infectious Diseases, University of California at Los Angeles, Los Angeles, California and <sup>6</sup>Department of Pathology and Laboratory Medicine, University of California at Los Angeles, Los Angeles, CA

### Abstract

**Background:** In 2015, an international outbreak of *Mycobacterium chimaera* infections among patients undergoing cardiothoracic surgeries was associated with exposure to contaminated LivaNova 3T heater-cooler devices (HCDs). From June 2017 to October 2020, the Centers for Disease Control and Prevention was notified of 18 patients with *M. chimaera* infections who had undergone cardiothoracic surgeries at 2 hospitals in Kansas (14 patients) and California (4 patients); 17 had exposure to 3T HCDs. Whole-genome sequencing of the clinical and environmental isolates matched the global outbreak strain identified in 2015.

**Methods:** Investigations were conducted at each hospital to determine the cause of ongoing infections. Investigative methods included query of microbiologic records to identify additional cases, medical chart review, observations of operating room setup, HCD use and maintenance practices, and collection of HCD and environmental samples.

**Results:** Onsite observations identified deviations in the positioning and maintenance of the 3T HCDs from the US Food and Drug Administration (FDA) recommendations and the manufacturer's updated cleaning and disinfection protocols. Additionally, most 3T HCDs had not undergone the recommended vacuum and sealing upgrades by the manufacturer to decrease the dispersal of *M. chimaera*-containing aerosols into the operating room, despite hospital requests to the manufacturer.

**Conclusions:** These findings highlight the need for continued awareness of the risk of *M. chimaera* infections associated with 3T HCDs, even if the devices are newly manufactured. Hospitals should maintain vigilance in adhering to FDA recommendations and the manufacturer's protocols and in identifying patients with potential *M. chimaera* infections with exposure to these devices.

(Received 16 June 2021; accepted 14 August 2021)

*Mycobacterium chimaera* is a slow-growing nontuberculous mycobacteria (NTM) and a member of the *Mycobacterium avium* complex (MAC). *M. chimaera* is commonly found in the environment, such as soil and water sources, and typically causes infection in patients who are immunocompromised or have underlying respiratory diseases.<sup>1</sup> In 2015, an international outbreak of *M. chimaera* infections among patients undergoing cardiothoracic surgeries was associated with exposure to contaminated LivaNova

3T heater-cooler devices (HCDs) (formerly Stöckert 3T heater-cooler system).<sup>2–5</sup> An HCD is used to warm and cool the patient's blood during a cardiopulmonary bypass.<sup>6</sup> Although water in the HCD water circuits does not come into direct contact with the patient, the 3T HCDs were likely contaminated at the production site and were found to disperse *M. chimaera*-containing aerosols from the internal water tanks into the operating room through the exhaust vent,<sup>7</sup> likely leading to patient infection. In response to the outbreak, the US Food and Drug Administration (FDA) issued a safety communication in October 2015 with recommendations for the use of HCDs.<sup>8</sup> In October 2018, the manufacturer released updated disinfection protocols and introduced device upgrades to reduce the risk of airborne transmission of NTM from 3T HCDs.<sup>9</sup>

On July 14, 2017, the Kansas Department of Health and Environment (KDHE) notified the Centers for Disease Control

**Author for correspondence:** Kerui Xu, E-mail: [kerui.xu@fda.hhs.gov](mailto:kerui.xu@fda.hhs.gov). Or Matthew B. Crist, E-mail: [cwu0@cdc.gov](mailto:cwu0@cdc.gov)

<sup>a</sup>Authors of equal contribution.

**Cite this article:** Xu K, et al. (2021). *Mycobacterium chimaera* infections among cardiothoracic surgery patients associated with heater-cooler devices—Kansas and California, 2019. *Infection Control & Hospital Epidemiology*, <https://doi.org/10.1017/ice.2021.396>

and Prevention (CDC) of *M. chimaera* infections in 2 patients who were exposed to 3T HCDs at hospital A from April to June 2017. In response to this cluster, on July 1, 2017, hospital A replaced all 5 of its HCDs with 5 new loaner 3T HCDs that were manufactured after September 2014 (manufacture dates of April–May 2017), the date after which FDA determined newly manufactured 3T HCDs as having lower risk of *M. chimaera* contamination due to procedure changes in the production line.<sup>10</sup> Despite this measure, KDHE notified the CDC of 11 additional patients identified by hospital A with *M. chimaera* infections associated with cardiothoracic surgeries from February to December 2019. On December 3, 2019, at the request of the KDHE, a CDC team joined KDHE and hospital staff to perform an onsite investigation to determine the cause of ongoing infections.

On November 5, 2019, the Los Angeles County Department of Public Health (LACDPH) notified CDC of *M. chimaera* surgical site infections in 2 patients exposed to 3T HCDs during bilateral orthotopic lung transplantation at hospital B from February 2017–March 2018. Subsequently, hospital B identified 2 additional patients with *M. chimaera* infections, who had undergone cardiothoracic surgery with exposure to 3T HCDs. The 4 patients were identified with *M. chimaera* infections from September 2018–October 2020. All had undergone cardiothoracic surgery with 3T HCDs manufactured after September 2014 (manufacture dates of December 2014–September 2017). On December 6, 2019, LACDPH staff joined hospital staff to conduct an onsite investigation.

## Methods

### Case definition

A case was defined as isolation of *M. chimaera* (or MAC that did not undergo further species identification) from a nonrespiratory specimen collected after January 1, 2010, in a patient who had undergone cardiothoracic surgery.

### Kansas investigation

To identify additional cases, investigators queried microbiology records to identify MAC isolates from nonrespiratory specimens of patients who had undergone cardiothoracic surgeries using HCDs, with a culture date from July 2017 to December 2019. July 2017 was the earliest date that microbiology records were available for review due to changes in the hospital's microbiological data records system.

The investigators reviewed medical charts and abstracted data on patient demographics, underlying medical conditions, signs and symptoms, sources of specimen culture, clinical diagnosis, and procedures performed. To assess operating room setup and positioning of HCDs prior to and during surgery, investigators observed 2 open-chest cardiac surgeries in which HCDs were in use and inspected the 5 HCDs in circulation. To assess HCD maintenance practices, investigators reviewed the manufacturer's instructions for use (IFUs)<sup>11</sup> and inspected hospital A's practices for cleaning and disinfection of HCDs, processes for filling and draining HCDs, mitigation measures undertaken to minimize potential exposure of *M. chimaera*-containing aerosols, and implementation of manufacturer-recommended device upgrades of vacuum cannister installation and internal sealing of water tanks.<sup>6,9</sup>

Sample collection was performed on 1 HCD with manufacturer-recommended device upgrades and 1 HCD without upgrades. *M. chimaera* cultures were obtained from (1) air samples collected

while HCDs were operational, (2) swab samples from the HCD water tanks and surfaces of operating room equipment, and (3) water samples from HCDs and operating room scrub sinks. Whole-genome sequencing (WGS) was performed by the CDC Division of Healthcare Quality Promotion (DHQP) to determine genetic relatedness of the clinical and environmental isolates.

### California investigation

The investigators observed the placement of HCDs in the operating room and inspected the 2 HCDs in circulation. To assess HCD maintenance practices, investigators inspected hospital B's cleaning and disinfection of HCDs to ensure consistency with FDA recommendations and the manufacturer's IFU,<sup>6,11</sup> as well as implementation of manufacturer-recommended device upgrades.<sup>6,9</sup> WGS was performed by the CDC DHQP to determine the genetic relatedness of the clinical isolates.


## Results

### Kansas investigation

One additional case was identified through retrospective case finding; in total, 14 patients with *M. chimaera* infection met the case definition. A medical record review identified 11 patients (79%) with history of cardiothoracic surgery prior to the first culture date (mean number of days from surgery to culture, 191 days; range, 38–491). The other 3 patients did not have prior cardiothoracic surgery, and their only exposure to HCD was during the index surgery when the specimen that tested positive for *M. chimaera* was collected (Fig. 1). The most common presenting symptoms were drainage at the surgical incision (n = 8, 57%), fatigue (n = 6, 43%), and shortness of breath (n = 6, 43%). The most common infection type was surgical site infection (n = 9, 64%) (Table 1). Most patients required surgical debridement to treat the infection (n = 8, 57%). The only death occurred in a patient placed in palliative care due to metastatic cancer, and this death was not attributed to *M. chimaera* infection.

During observation of cardiac surgeries, only 1 HCD at hospital A had undergone the manufacturer-recommended device upgrades of vacuum cannister installation and internal sealing of water tanks,<sup>6,9</sup> despite hospital A's request to the manufacturer. The HCD was positioned toward the surgical bed and instrument table and was turned on prior to the patient's arrival into the operating room. Once the patient was intubated and draped for skin incision, the HCD was repositioned with the exhaust vent directed at a 45° angle away from the surgical bed, but not toward the operating room exhaust, and it was not placed outside of the laminar airflow as recommended by FDA and the manufacturer's IFU due to operating room design and limited space.<sup>6,11</sup> During skin closure, the HCD was repositioned to its original configuration with the exhaust vent facing the surgical bed and instrument table. In October 2018, hospital A began draining the HCD water tank daily and discontinued daily monitoring of hydrogen peroxide concentration and disinfection of the water circuits as recommended by the manufacturer,<sup>9,11</sup> with the assumption that daily draining of water tanks would decrease the risk of microbial growth in the water circuits and obviate the need for routine disinfection. Additionally, filling and draining of the HCDs were performed inside the operating room, and water was observed on the operating room floor due to overflow of HCDs or to the change in tubing.

For the HCD without device upgrades, *M. chimaera* was recovered from (1) air samples collected at the surgical bed and



**Fig. 1.** Timeline of events from date of cardiothoracic surgery to date of collection of the first *Mycobacterium chimaera*-positive clinical culture, Kansas and California, February 2017–October 2020. Patients with no *M. chimaera* HCD-related infection did not have a prior cardiothoracic surgery. Samples collected during index surgery were positive for *M. chimaera*, but patients did not develop clinical infection, indicating that *M. chimaera*-containing aerosols likely contaminated the specimens during the index surgery. Note: KS, Kansas; CA, California; PT, patient; HCD, heater-cooler device.

0.30 m (1 foot) away from the HCD exhaust, (2) swabs of brass connectors used to connect the HCD to the heart-lung machine, and (3) HCD water samples. For the HCD with device upgrades, which was not associated with any cases, *M. chimaera* was recovered from HCD water samples but not from air or swab samples.

The WGS of 11 available *M. chimaera* patient isolates and 13 available *M. chimaera* environmental isolates indicated that all were closely related to each other and to previous isolates from the international outbreak identified in 2015 (0–13 single nucleotide variants [SNVs] across 93.05% core genome) (Fig. 2).<sup>12</sup>

### California investigation

Onsite observations at hospital B revealed that the HCD exhaust vent was directed at a 90° angle away from the surgical field and toward the operating room exhaust. The 2 HCDs in circulation had the appropriate manufacturer-recommended device upgrades of vacuum cannister installation and internal sealing of water tanks.<sup>6,9</sup> However, at the time of surgery for the 4 cases, the HCDs had not undergone the recommended device upgrades and had not been disinfected prior to use for the first time as recommended by the manufacturer's IFU.<sup>11</sup> No samples from HCDs or the operating room environment were collected.

The WGS of 3 available *M. chimaera* patient isolates indicated that the isolates were closely related to each other and to previous isolates from the international outbreak identified in 2015 (2–13 SNVs, across 93.05% core genome) (Fig. 2).<sup>12</sup>

### Discussion

These investigative findings at 2 hospitals provide strong evidence of persistent contamination of 3T HCDs with *M. chimaera* and

ongoing patient risk of infection even with the use of devices manufactured after September 2014. Hospitals may consider that using newer HCDs poses lower infection risk than HCDs manufactured prior to September 2014,<sup>10</sup> but our findings highlight that strict adherence to FDA recommendations and the manufacturer's IFU are imperative to mitigate risk. Once the HCD is turned on, the HCD exhaust should be directed away from the sterile field, instrument tables, and surgical bed, even if the patient has not yet been placed on the bed, to prevent *M. chimaera*-containing aerosols from contaminating the operating room environment.<sup>6,11</sup> Ideally, HCDs should be positioned with the exhaust vent facing the air exhaust in the operating room and should be placed outside the laminar airflow of the operating room.<sup>6,11</sup> As demonstrated by our environmental sampling results, device upgrades likely reduced the number of aerosolized organisms to below detectable limits. 3T HCDs should undergo the manufacturer-recommended device upgrades of vacuum cannister installation and internal sealing of water tanks.<sup>6,9</sup> Hospitals should consider prioritizing the use of HCDs with these device upgrades and should contact the manufacturer as soon as possible. The manufacturer should ensure that the recommended device upgrades are implemented in a timely manner.

HCD tubing and water basins retain water despite draining, promoting biofilm growth.<sup>3,13</sup> HCDs should be disinfected prior to use for the first time and every 14 days, even if tanks are drained daily, to prevent microbial growth.<sup>11</sup> Hydrogen peroxide concentration in the water circuit should be monitored on a daily basis, before HCD use, and even if the HCD is not in routine use.<sup>9,11</sup> Deviation from the IFU may place patients at greater risk for infections. In addition, hospitals should consider filling and draining HCDs outside the operating room to avoid splashing and contamination of the surgical environment.<sup>11</sup>

**Table 1.** Patient Demographics and Clinical Characteristics of Patients With *Mycobacterium chimaera* Infection Associated With Cardiothoracic Surgery, Kansas and California, February 2017–October 2020

Characteristic	Total (n = 18), No. (%)		Kansas (n = 14), No. (%)		California (n = 4), No. (%)	
<b>Demographics</b>						
Age, median y (range)	68	(19–84)	68.5	(25–84)	37	(19–71)
Sex, male	12	(67)	8	(57)	4	(100)
Race, white	14	(78)	12	(86)	2	(50)
BMI, mean (range)	27.2	(19.8–37.4)	28.7	(20.2–37.4)	22.2	(19.8–25.3)
<b>Underlying medical conditions</b>						
Cardiovascular disease	13	(72)	9	(64)	4	(100)
Dermatologic condition	8	(44)	8	(57)	0	(0)
Chronic metabolic disease/diabetes	5	(28)	5	(36)	0	(0)
Malignancy	4	(22)	3	(21)	1	(25)
Immunocompromised	4	(22)	2	(14)	2	(50)
Chronic lung disease	4	(22)	2	(14)	2	(50)
Renal disease	2	(11)	2	(14)	0	(0)
Neurologic condition	2	(11)	2	(14)	0	(0)
<b>Signs and symptoms</b>						
Drainage at surgical incision	9	(50)	8	(57)	1	(25)
Fatigue	8	(44)	6	(43)	2	(50)
Shortness of breath	8	(44)	6	(43)	2	(50)
Swelling	5	(28)	3	(21)	2	(50)
Cough	3	(17)	3	(21)	0	(0)
Redness	3	(17)	2	(14)	1	(25)
Night sweats	3	(17)	2	(14)	1	(25)
Bone pain	2	(11)	2	(14)	0	(0)
Fever	2	(11)	1	(7)	1	(25)
Nausea	1	(6)	1	(7)	0	(0)
Abdominal pain	1	(6)	1	(7)	0	(0)
Chest pain	1	(6)	0	(0)	1	(25)
Significant weight loss	1	(6)	0	(0)	1	(25)
Hemoptysis	1	(6)	0	(0)	1	(25)
Hematemesis	1	(6)	0	(0)	1	(25)
<b>Sources of specimen culture</b>						
Sternal wounds	10	(56)	6	(43)	4	(100)
Superficial wounds	5	(28)	3	(21)	2	(50)
Heart tissue	4	(22)	3	(21)	1	(25)
Deep fluid collections	2	(11)	2	(14)	0	(0)
Bone marrow	1	(6)	0	(0)	1	(25)
Blood	1	(6)	0	(0)	1	(25)
Stool	1	(6)	0	(0)	1	(25)
Sputum	1	(6)	0	(0)	1	(25)
<b>Clinical diagnosis</b>						
Surgical-site infections <sup>a</sup>	12	(67)	9	(64)	3	(75)
No HCD-related infections <sup>b</sup>	3	(17)	3	(21)	0	(0)
Endocarditis	2	(11)	1	(7)	1	(25)
Pneumonia <sup>c</sup>	1	(6)	1	(7)	0	(0)

(Continued)

Table 1. (Continued)

Characteristic	Total (n = 18), No. (%)		Kansas (n = 14), No. (%)		California (n = 4), No. (%)	
<b>Primary procedures performed prior to culture of <i>M. chimaera</i></b>						
Coronary artery bypass surgery	6	(33)	6	(43)	0	(0)
Aortic valve replacement	4	(22)	3	(21)	1	(0)
Ventricular assist device placement	2	(11)	1	(7)	1	(25)
Lung transplantation	2	(11)	0	(0)	2	(50)
Aortic root replacement	1	(6)	1	(7)	0	(0)
Ventriculomyotomy	1	(6)	1	(7)	0	(0)
Pericardial window	1	(6)	1	(7)	0	(0)
Heart transplantation	1	(6)	1	(7)	0	(0)

Note. HCD, heater-cooler device; BMI, body mass index.

<sup>a</sup>Of the 12 patients with surgical site infections, 4 had sternal osteomyelitis.

<sup>b</sup>Samples collected during index surgery were positive for *M. chimaera*, but patients did not develop clinical infection, indicating that *M. chimaera*-containing aerosols likely contaminated the specimens during the index surgery; 2 of the patients underwent aortic valve replacement and 1 patient underwent a pericardial window.

<sup>c</sup>This was the documented clinical diagnosis, but the specimen culture was collected from pleural fluid.




Fig. 2. Maximum likelihood phylogenetic tree of *Mycobacterium chimaera* environmental and clinical isolates in patients with *M. chimaera* infection associated with cardiothoracic surgery, Kansas and California, February 2017–October 2020. *M. chimaera* was recovered from 3 water samples only (not from air or swab samples) of the Kansas HCD that had undergone the October 2018 manufacturer-recommended device upgrades.<sup>9</sup> No patients who had undergone cardiothoracic surgery with the upgraded HCD developed *M. chimaera* infection. Note: KS, Kansas; CA, California; HCD, heater-cooler device.

In 2016, the CDC advised hospitals to notify patients with exposure to 3T HCDs of the potential risk of infection to facilitate early detection of *M. chimaera* infections.<sup>14</sup> Hospitals that performed an initial notification but have identified HCD-associated patient infections among patients who had undergone cardiothoracic surgeries after the notification should update the notification to increase awareness of infection risk to patients not included in the initial notification. These hospitals may also consider using

preoperative informed consent to educate patients about the potential infection risk associated with 3T HCDs, as well as the signs and symptoms of infection, at least until all recommended mitigation steps have been implemented. Healthcare providers should continue to consider *M. chimaera* infection when evaluating cardiothoracic surgery patients presenting with surgical site infections or signs or symptoms of disseminated NTM infection.<sup>14</sup>

The CDC and FDA continue to be actively engaged in evaluating the risk of *M. chimaera* infections associated with 3T HCDs and monitoring for reports of new infections.<sup>6</sup> Although the current investigation involved *M. chimaera* infections associated with 3T HCDs, hospitals should follow FDA recommendations for the use of any HCD to reduce NTM infection risk to patients.<sup>15</sup> If hospitals or healthcare providers identify patients with NTM infections associated with exposure to HCDs, they should submit an FDA MedWatch report<sup>16</sup> and should notify public health authorities.

**Acknowledgments.** The authors thank the following individuals for their contributions: Michelle Adamczyk, Cecilia Bardossy, MD, Erin Breaker, MS, Bryan Christensen, PhD, Alison Laufer Halpin, PhD, Hollis Houston, Adrian Lawsin, MS, Carrie Sanders, MS, Valerie Stevens, Matthew Stuckey, PhD, Erisa Sula, MS, Division of Healthcare Quality Promotion, CDC; Justin Blanding, MPH, Sheri Tubach, MPH, Kansas Department of Health and Environment; Omer Beaird, MD, Kim De La Cruz, MS, Amy Hallmark, MS, Ruel Mirasol, Curtis Murata, Susan Realegeno, PhD, Shaunte Walton, MS, University of California at Los Angeles; Susan Hathaway, MPH, Amy Marutani, MPH, Steve Moon, Los Angeles County Department of Public Health; Rachael Liesman, PhD, Jamie Newberry, Jennifer Pennington, University of Kansas Medical Center; Kelly Bauer, MS, Angela Dixon-Allamby, Nicole Gillette, Suvajyoti Guha, PhD, Elaine Mayhall, PhD, Jon Weeks, PhD, Catherine Wentz, US Food and Drug Administration.

**Financial support.** No financial support was provided relevant to this article.

**Conflicts of interest.** All authors report no conflicts of interest relevant to this article.

## References

1. Trudzinski FC, Schlotthauer U, Kamp A, *et al*. Clinical implications of *Mycobacterium chimaera* detection in thermoregulatory devices used for extracorporeal membrane oxygenation (ECMO), Germany, 2015 to 2016. *Euro Surveill* 2016;21(46):30398.
2. Perkins KM, Lawsin A, Hasan NA, *et al*. Notes from the Field. *Mycobacterium chimaera* contamination of heater-cooler devices used in cardiac surgery—United States. *Morb Mortal Wkly Rep* 2016;65:1117–1118.
3. Lyman MM, Grigg C, Kinsey CB, *et al*. Invasive nontuberculous mycobacterial infections among cardiothoracic surgical patients exposed to heater-cooler devices. *Emerg Infect Dis* 2017;23:796–805.
4. Sax H, Bloemberg G, Hasse B, *et al*. Prolonged outbreak of *Mycobacterium chimaera* infection after open-chest heart surgery. *Clin Infect Dis* 2015; 61:67–75.
5. Jarashow MC, Terashita D, Balter S, Schwartz B. Notes from the field: *Mycobacteria chimaera* infections associated with heater-cooler unit use during cardiopulmonary bypass surgery—Los Angeles County, 2012–2016. *Morb Mortal Wkly Rep* 2019;67:1428–1429.
6. Update: reduce the risk of cardiac surgery infection while using the LivaNova heater-cooler system 3T: FDA safety communication. US Food and Drug Administration website. <https://www.fda.gov/medical-devices/safety-communications/update-reduce-risk-cardiac-surgery-infection-while-using-livanova-heater-cooler-system-3t-fda-safety>. Published 2020. Accessed August 2, 2021.
7. Haller S, Höller C, Jacobshagen A, *et al*. Contamination during production of heater-cooler units by *Mycobacterium chimaera* potential cause for invasive cardiovascular infections: results of an outbreak investigation in Germany. *Euro Surveill* 2016;21(17):pii:30215.
8. Nontuberculous *Mycobacterium* infections associated with heater-cooler devices: FDA safety communication. US Food and Drug Administration website. <https://wayback.archive-it.org/7993/20170404182156/https://www.fda.gov/MedicalDevices/Safety/AlertsandNotices/ucm466963.htm>. Published 2015. Accessed August 2, 2021.
9. LivaNova Deutschland GmbH. Mitigating potential cardiac surgery infection risks. LivaNova website. <https://www.livanova.com/LivaNova-Public/media/Images/Hydrogen-Peroxide-Monitoring-and-Design-Upgrade-Customer-Letter-r1.pdf?ext=.pdf>. Published 2018. Accessed July 30 2021.
10. Update: availability of deep-cleaning service of certain LivaNova PLC (formerly Sorin Group Deutschland GmbH) Stockert 3T heater-cooler systems in the US: FDA safety communication. US Food and Drug Administration website. <https://www.fda.gov/medical-devices/safety-communications/update-availability-deep-cleaning-service-certain-livanova-plc-formerly-sorin-group-deutschland-gmbh>. Published 2018. Accessed August 1, 2021.
11. Heater-cooler system 3T operating instructions (version 21). LivaNova Deutschland GmbH website. [https://livanovamediaproduct.azureedge.net/livanova-media/livanova-public/media/resources01/cp\\_ifu\\_16-xx-xx\\_usa\\_021.pdf?ext=.pdf](https://livanovamediaproduct.azureedge.net/livanova-media/livanova-public/media/resources01/cp_ifu_16-xx-xx_usa_021.pdf?ext=.pdf). Published 2020. Accessed November 16, 2020.
12. Hasan NA, Lawsin A, Perry KA, *et al*. Complete genome sequence of *Mycobacterium chimaera* strain CDC2015-22-71. *Genome Announc* 2017;5(31):e00693–17.
13. Garvey MI, Ashford R, Bradley CW, *et al*. Decontamination of heater-cooler units associated with contamination by atypical mycobacteria. *J Hosp Infect* 2016;93:229–234.
14. CDC advises hospitals to alert patients at risk from contaminated heater-cooler devices used during cardiac surgery. Centers for Disease Control and Prevention website. <https://emergency.cdc.gov/han/han00397.asp>. Published 2016. Accessed December 3, 2020.
15. Recommendations for the use of any heater cooler device. US Food and Drug Administration website. <https://www.fda.gov/medical-devices/what-heater-cooler-device/recommendations-use-any-heater-cooler-device>. Published 2020. Accessed March 21, 2021.
16. Medical device reporting (MDR): how to report medical device problems. US Food and Drug Administration website. <https://www.fda.gov/medical-devices/medical-device-safety/medical-device-reporting-mdr-how-report-medical-device-problems>. Published 2020. Accessed August 1, 2021.