# Lawrence Berkeley National Laboratory

**Recent Work** 

**Title** CYLINDER ASSY, LARGE RADIUS COARSE FIELD CAGE

Permalink https://escholarship.org/uc/item/6wv048sb

Author Nesbitt, Dale.

Publication Date 1981-06-01



# Lawrence Berkeley Laboratory UNIVERSITY OF CALIFORNIA

Engineering & Technical Services Division


RECEIVED LAWRENCE BERKELEY LABORATORY

APR 21 1983

LIBRARY AND DOCUMENTS SECTION



Not to be taken from this room



-09-(127

### LEGAL NOTICE

This book was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Lawrence Berkeley Laboratory is an equal opportunity employer.

١.

# DISCLAIMER

This document was prepared as an account of work sponsored by the United States Government. While this document is believed to contain correct information, neither the United States Government nor any agency thereof, nor the Regents of the University of California, nor any of their employees, makes any warranty, express or implied, or assumes any legal responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by its trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof, or the Regents of the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof or the Regents of the University of California.

LAWRENCE BERKELEY	'LABORAT	ORY - UNIVERSITY	OF CALIFORNIA	CODE	SERIAL	PA
ENGIN	EER	ING N	IOTE	P40406	M5664	1 0
UTHOR Dale Men	DE	PARTMENT		LOCATION	DATE	<b>1</b>
Dale Nesbitt	•	Mechanical	Engineering	Berkeley	24 June	1981
PEP-4						
FIELD CAGES (	TPC)					
ITLE						<u></u> .
CYLINDER ASSY	, LARGE	KADIUS CUAKSE	E FIELD LAGE			
The purpose (	of this	note is to	record pertir	nent informat	ion concer	rnina
the assembly Drawing Nos.	work a	done at LBL o	on the L.R.C.	F.C.which is	specifie	d on
	-		storical in 1	nature and w	vill snell	out
some of our	failure	s and frustr	ations as wel	1 as the su	ccesses.	Most
of this work	was do	one with <u>NO d</u>	rawings or pr	ocedures worl	ked out a	head
and Dale Nesh	ign note itt and	es were kept many nictures	as well as ti s taken. These	Ime permitted	by Fred H	Perry
looseleaf no	te book	which will	be kept by D	e are in two ). Nesbitt ou	larye r in the n	rint
room. Most	of the	neonle who w	worked on the	accombly and	s chown in	
of the photon	or the	people mile	Morked on the	assembly are	E SHOWIL TH	one
of the photos.	•	people mid	NOTREE ON CHE		E SHOWN TH	one
of the photos.	•					
of the photos.	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	S NOT covere	d in this not			
of the photos. Electrical te	• sting 1	<u>S NOT</u> coverent to the physical second seco	d in this not	te. This wa		
of the photos. Electrical te	• sting 1	<u>S NOT</u> coverent to the physical second seco	d in this not	te. This wa		
of the photos. Electrical te	• sting 1	<u>S NOT</u> coverent to the physical second seco	d in this not	te. This wa		
of the photos. Electrical te	• sting 1	<u>S NOT</u> coverent to the physical second seco	d in this not	te. This wa		
of the photos. Electrical te	• sting 1	<u>S NOT</u> coverent to the physical second seco	d in this not	te. This wa		

\* All dimensions in inches unless noted

Sec. A

	NCE BERKELEY LABORA			CODE	SERIAL	PAGE
UTHOR	NGINEE	RING N	IOTE	P40406	M5664	2 OF
-	e Nesbitt	1	Engineering	Berkeley	24 June 198	1
			-		_	-
some The	e of the more im re is much more	portant problem information in	will only be a m areas and of t the note books er (including me	he solution and photos h	s (if anv).	
1)	Demandreling: We finally had	The force required to cut the main the termination of the second se	uired to pull th ndrel apart.	e wedges was	s excessive.	
2)	The end of the special setup	insulation was and cut it squa	s not cut square are.	by Sheldal,	, we made a	
3)		as not to print .043 on the dia	t, either in len ameter upon bein	gth or I.D. g removed fr	It shrank rom the	
4)	made it very d	ifficult to fla	of spec., espec aten during asse hold them flat.	ially on fla mbly and epo	atness which oxying.	
5)	The drilling f Finally we dec sectors to fit	ided to use the	ny sectors did n e drilling fixtu	ot match up re and force	well. the dummy	
6)	We found that well as design new fixtures.	the line up and ed so we revise	l drilling for t d the procedure	he sectors d s and design	id not work ned several	
7)	aggravated by	pulling the wed	l - which may ha lges out. In the or the center s	e end this m	ade it	•
8)	The cylinder is weight.	s very weak, it	sags almost 1/2	2" under its	own	
9)	There were a nu build up the ir of time.	umber of voids aner cylinder,	between the G - they were filled	10 boards u 1 at the cos	sed to t of lots	
10)	about 100 were under pressure bubbles had for	e filled. Afte and vacuum it med. After te	nder the Kapton, r the initial el was found that a sting of samples ded to pierce th	lectrical te a large numb s (report pa	st (Building) er of	5)
11)	Soldering of th task. There sh	e sockets into ould be a bett	the ferrules wa er way.	is a very di	fficult	
12)	Measurements wa to make them ar be covered in m	id then whether	ably the biggest to believe them	or not. T	First how his is to	

LAWRENCE BERKELEY LABO	RATORY . UNIVERSITY OF CALIFORNIA.	CODE	SERIAL	PAGE
ENGINE	ERING NOTE	P40406	M5664	3 of 6
AUTHOR	DEPARTMENT	LOCATION	DATE	
Dale Nesbitt	Mechanical Engineering	Berkeley	24 June 198	31

# Measurements:

The original concept was that most of the measurements and assembly of the end rings, supports etc would be done with the cylinder vertically on a flat table (A 8' x 8' table was purchased). There had been holes drilled in 6 places in the center groove (Drawing No. 198854) which would define the center plane. Then the end rings would be placed on equal distance from and parallel to these. The center supports were to be positioned in line with these holes. However, it did not work out that way or easy. First the cylinder was neither the correct I.D., length nor round. The height of the six holes (pins installed) were measured from the flat table and 3 selected to define a plane (total variation between all 6 was .007 - remember the desired maximum error is  $\pm$ .004). The end planes were positioned, held flat as well as possible and epoxied. (See notes from 7-2 to 7-21 1980)

Measurements taken shortly afterwards indicated all was well. But later while trying to line up the location of the holes for the sectors from end to end it was observed that the cylinder was not perpendicular to the end rings. It was skewed about .030. An attempt was made to compensate for this and all the holes drilled. Due to this and to the out of tolerance cylinder it was decided that measurements of the I.D. and center supports and sector mounting surfaces had to be made with the cylinder in its normal horizontal position with sectors in place. This required more fixtures. The measurements were made using a indicator or depth mike mounted on arm(s) that divoted around a tube which was held in the center of the small radius end rings (which were not on the S.R.C.F.C.) which were held by the dummy sectors. There are sketches and photos of this.

Based on these measurements all the supports were reworked or remade and installed. See 19Q2736. However, the problem was always one of (a) being able to repeat a measurement - especially longitudinly and (b) even if it repeated there was no way to check the absolute accuracy.

The entire Field Cage assembly was completed after the L.R.C.F.C. (19Q2736) assy. was done using dummy end rings for the S.R.F.C. and with out trying to precisely align the L.R.F.F.Cs or check for axial line up of the large and small radius end rings. After the entire assembly was successfully tested (in Building 6) up to 100,000 volts it was taken back to Building 77 for the final precision lineup.

The items covered in this Engineering Note took from 6-10-80 to 12-19-80 with 2 to 5 assembly technicians so obviously this only covers it very lightly.

LAWRENCE BERKELEY LABO	RATORY - UNIVERSITY OF	CALIFORNIA,	CODE	SERIAL	PAGE
ENGINEE	ERING NO	DTE /	P40406	M5664	4 of 6
ITHOR	DEPARTMENT		LOCATION	DATE	
Dale Nesbitt	Mechanical Engi	neering	Berkeley	24 June 19	931
		<u> </u>		-	
	2000 - 120 -	·		· · · · · · · · · · · · · · · · · · ·	
· ·					
				ELEY LABORATORY oom: 6204Ext.: 652	1
					-

May 4, 1981

#### MEMORANDUM

TO: Distribution

FROM: S. Sherman and D. Nesbitt &

SUBJECT: Results of the H.V. Field Cage Bubbling Tests

After the high voltage tests in Bldg. 6 were completed it was observed that the kapton-epoxy laminate on the inside of the coarse field cage had developed bubbles. The bubbles varied in size with the largest being  $1" \times 1"$  with a depth of about 0.010/0.015". These bubbles might conceivably grow so large as to disturb the high voltage field.

In an attempt to understand and limit the growth of bubbles on the field cage, several samples of the field cage material were tested in an environment which simulated the pressure and vacuum conditions of the high voltage test. The idea being that bubbles formed as a result of compression and decompression during the H.V. tests.

 $4" \times 4"$  samples of either 3 mil or 1 mil kapton on 1/8" FR-4 fiberglass were fabricated. Some were deliberately flawed. Some had areas where there was a lack of epoxy; some had small bubbles. The samples were placed in a test vessel and pumped down for 5 min. to 48 hrs., the vacuum reaching 25" Hg and 350 millitorr respectively. Then the vessel was filled to 135 psig with either 100% Argon or 80% Argon-20% Methane. The samples were kept at pressure for times ranging from 4.5 hrs. to 1 week. The vessel was vented to 1 atm. in 2 to 5 minutes, pumped down to 29 in Hg of vacuum and then backfilled with air. The samples were removed and immediately examined. Two samples from each test were kept at air for several days after decompression and checked daily under a microscope for signs of bubble growth. It should be pointed out that the 2-5 min. decompression in the bubbling test was much faster than the 20 hrs. in the high voltage test. Four samples each spent a total of 660 hrs. at pressure. In all there were 14 samples tested.

The samples showed no bubbling on the order that the field cage displayed. The largest bubbles were about  $1/4'' \times 1/4'' \times 0.010''$  deep in the 1 mil samples and  $1/8'' \times 1/8'' \times 0.005''$  in the 3 mil samples. In no case was there an increase in area, nor did any bubbles form except when there was no epoxy to start with. Bubbles which were lanced returned to their original size. The 3 mil samples in general showed less bubbling than the 1 mil samples. There seemed to be no difference in results produced by the 100% Argon and the mixed gas. Areas lacking epoxy developed small bubbles which, like all other observed bubbles, reached a limit to their growth.

UNIVERSITY OF CALIFORNIA- (Letterhead for interdepartmental use)

N.-3220-20(Rov 8/71)

٤,

LAWRENCE BERKELEY LABOR	RING NOTE	<sup>собе</sup> Р40406	M5664	PAGE 5 of 6
Dale Nesbitt	Mechanical Engineering	Berkeley	24 June 19	81

Distribution May 4, 1981 Page 2

Our results suggest that there is something peculiar to the laminate in the field cage which allowed the bubbles to form. We were not able to produce bubbles on the order that was seen in the field cage even though our test conditions were more extreme than the H.V. test conditions. In addition, the three sections of the field cage display differing amounts of bubbling. They were fabricated at different times and this suggests that some aspect of the fabrication changed which allowed for greater or lesser susceptibility to bubbling even though care was taken to keep the fabrication consistent.

Whatever the cause, lancing the bubbles will take care of existing bubbles. Bubbles formed in the future will most likely reach a terminal size and in any case may be lanced when the field cage is removed. It is not known, however, if any more bubbles will develop. This is something that should be looked at during the IR-2 tests.

## SS/DN:cg

Distribution:

- A. Bross
- L. E. Brown
- 0. Chamberlain
- 0. Draeger
- R. Madaras
- K. Mirk

LAWRENCE BERKELEY LABO	RATORY . UNIVERSITY OF CALIFORNIA.	CODE	SERIAL	PAGE
ENGINEERING NOTE		P40406	M5664	6 of 6
AUTHOR	DEPARTMENT	LOCATION	DATE	
Dale Nesbitt	Mechanical Engineering	Berkeley	24 June	1981

Conclusions/Recommendations:

- 1) The basic design concepts of the TPC (which includes the Field Cages) is inappropriate to hold the requested tolerances of  $\pm .004$  (1/10 mm).
- 2) Much more real Engineering needs to go into conceptual design, calculations, pre-planning and prototyping as appropriate before the design is released. Part of this would be to present a reasonable estimate of costs versus precision to physics so that alternate ways to acheive the end goal(s) could be considered. Trying to make it work as we did is the worst way.
- 3) It would have been a lot worse without the expert assistance of Fred Perry and the willing cooperation and many good suggestions from all the assembly and machine shop people, especially Bill Baldock, Roy Oki, Jon Wirth, Al Barone and Otto Draeger.

This report was done with support from the Department of Energy. Any conclusions or opinions expressed in this report represent solely those of the author(s) and not necessarily those of The Regents of the University of California, the Lawrence Berkeley Laboratory or the Department of Energy.

,

,

J

Reference to a company or product name does not imply approval or recommendation of the product by the University of California or the U.S. Department of Energy to the exclusion of others that may be suitable. TECHNICAL INFORMATION DEPARTMENT LAWRENCE BERKELEY LABORATORY UNIVERSITY OF CALIFORNIA BERKELEY, CALIFORNIA 94720

-

ч .

ч .

. .

. .