

Lawrence Berkeley National Laboratory

LBL Publications

Title

Corrigendum to Dynamic-temperature operation of metal-supported solid oxide fuel cells [J. Power Sources 395 (2018) 314–317]

Permalink

<https://escholarship.org/uc/item/3sq654n8>

Author

Tucker, Michael C

Publication Date

2021-04-01

DOI

10.1016/j.jpowsour.2021.229647

Peer reviewed

Corrigendum

Corrigendum to Dynamic-temperature operation of metal-supported solid oxide fuel cells

Journal of Power Sources 395 (2018) 314–317

Michael C. Tucker

Lawrence Berkeley National Laboratory, Energy Storage and Distributed Resources Division, 1 Cyclotron Rd, MS 62-203, Berkeley, CA, 94720, United States

The authors regret that a technical mistake has been discovered, which impacts the current density and power density reported in this article. Briefly, the mistake was caused by catalyst solution leaking out of the intended 1 cm² catalyzed area and depositing catalyst over the whole cell. As a result, the calculated current and power densities (total divided by the catalyzed area) were higher than reality because the measured current and power were dividing by the intended 1 cm² instead of the actual area including the leakage, which was approximately 5 cm². This issue is presented, analysed, and discussed in further detail in the supporting information of Reference 1.

The authors would like to apologise for any inconvenience caused.

[1] E. Dogdibegovic, Y. Cheng, F. Shen, R. Wang, B. Hu, J. Power Sources 489 (2021) 229439. <https://doi.org/10.1016/j.jpowsour.2020.229439>