UC Irvine

Western Journal of Emergency Medicine: Integrating Emergency Care with Population Health

Title

Images in Emergency Medicine: Pacemaker Extrusion Causing Chest Pain

Permalink

https://escholarship.org/uc/item/0s36k50t

Journal

Western Journal of Emergency Medicine: Integrating Emergency Care with Population Health, 9(2)

ISSN

1936-900X

Author

Arora, Sanjay

Publication Date

2008

Copyright Information

Copyright 2008 by the author(s). All rights reserved unless otherwise indicated. Contact the author(s) for any necessary permissions. Learn more at https://escholarship.org/terms

Peer reviewed

Images in Emergency Medicine: Pacemaker Extrusion Causing Chest Pain

Sanjay Arora, MD

LAC+USC Medical Center, Department of Emergency Medicine

Supervising Section Editor: Mark I. Langdorf MD, MHPE Submission history: Submitted May 23, 2007; Revision Received June 19, 2007; Accepted August 3, 2007. Reprints available through open access at www.westjem.org [WestJEM. 2008;9:126.]



Figure.

A 55-year-old Hispanic male had a pacemaker placed in Mexico approximately one year prior to presenting to the Emergency Department. He noticed minor discomfort in his left chest one month earlier but did not see a physician. The discomfort steadily increased and he saw a small piece of metal poking through the skin. He assumed it was a staple or something minor related to the surgery; however, it gradually increased in size over the next few weeks until he realized it was the pacemaker itself eroding though his chest wall. A cardiology consultation was called, and an EKG showed

that the pacemaker was still functioning normally. He was admitted with a plan for operative repair.

Pacemaker erosion or extrusion has been reported in 0.9% of patients receiving the device. The two main causes are infection and pressure necrosis. Infection has been shown to be reduced by antibiotic treatment during the peri-placement period, and pressure necrosis appears to be influenced largely by the size of the device, complexity of the connections and technical skill with which the pocket is created. After extrusion, the pacemaker should be considered contaminated and removed.

Address for correspondence: Sanjay Arora, MD Department of Emergency Medicine, LAC + USC Medical Center, 1200 N. State Street, Room 1011, Los Angeles, CA 90033. Email: sanjayar@usc.edu

REFERENCES

- Shapiro M, Hanon S, Schweitzer P. A Rare, Late Complication after Automated Implantable Cardioverter-Defibrillator Placement. *Indian Pacing and Electrophysiology Journal*. 2004; 213-216.
- Oneglia C, Gardini A, Benedini G, Rusconi C. Extrusion of a Regularly Stimulating Pacemaker. *International Journal of Cardiology*. 2007; 114:382-383.
- 3. Parsonnet V, Trivedi A. Pacemaker Extrusion. *Journal of the American Heart Association*.2000; 102:1192.