

Lawrence Berkeley National Laboratory

Recent Work

Title

Corrigendum to Durability of symmetric-structured metal-supported solid oxide fuel cells [J. Power Sources 369 (2017) 6–12] (Journal of Power Sources (2017) 369 (6–12), (S0378775317313022), (10.1016/j.jpowsour.2017.09.075))

Permalink

<https://escholarship.org/uc/item/7h13h5np>

Author

Tucker, MC

Publication Date

2021-04-30

DOI

10.1016/j.jpowsour.2021.229646

Peer reviewed

Corrigendum

Corrigendum to Durability of symmetric-structured metal-supported solid oxide fuel cells

Journal of Power Sources 369 (2017) 6-12

Michael C. Tucker

Lawrence Berkeley National Laboratory, Energy Storage and Distributed Resources Division, 1 Cyclotron Rd, MS 62-203, Berkeley, CA, 94720, United States

The authors regret that a technical mistake has been discovered, which impacts the current density and power density reported in this article. Briefly, the mistake was caused by catalyst solution leaking out of the intended 1 cm² catalyzed area and depositing catalyst over the whole cell. As a result, the calculated current and power densities (total divided by the catalyzed area) were higher than reality because the measured current and power were dividing by the intended 1 cm² instead of the actual area including the leakage, which was approximately 5 cm². This issue is presented, analysed, and discussed in further detail in the supporting information of Reference 1.

The authors would like to apologise for any inconvenience caused.

[1] E. Dogdibegovic, Y. Cheng, F. Shen, R. Wang, B. Hu, J. Power Sources 489 (2021) 229439. <https://doi.org/10.1016/j.jpowsour.2020.229439>

DOI of original article: 10.1016/j.jpowsour.2017.09.075

Michael C. Tucker
mctucker@lbl.gov