Lawrence Berkeley National Laboratory

LBL Publications

Title

Corrigendum to high performance metal-supported solid oxide fuel cells with infiltrated electrodes [Journal of Power Sources 410-411 (2019) 91-98]

Permalink

https://escholarship.org/uc/item/0tg6889g

Authors

Dogdibegovic, Emir Wang, Ruofan Lau, Grace Y et al.

Publication Date

2021-05-01

DOI

10.1016/j.jpowsour.2021.229648

Peer reviewed

Corrigendum

Corrigendum to High performance metal-supported solid oxide fuel cells with infiltrated electrodes

Journal of Power Sources 410–411 (2019) 91–98

Emir Dogdibegovic, Ruofan Wang, Grace Y. Lau, Michael C. Tucker

Lawrence Berkeley National Laboratory, Energy Storage and Distributed Resources Division, 1 Cyclotron Rd, MS 62-203, Berkeley, CA, 94720, United States

The authors regret that a technical mistake has been discovered, which impacts the current density and power density reported in this article. Briefly, the mistake was caused by catalyst solution leaking out of the intended 1 cm² catalyzed area and depositing catalyst over the whole cell. As a result, the calculated current and power densities (total divided by the catalyzed area) were higher than reality because the measured current and power were dividing by the intended 1 cm² instead of the actual area including the leakage, which was approximately 5 cm². This issue is presented, analysed, and discussed in further detail in the supporting information of Reference 1.

The authors would like to apologise for any inconvenience caused.

[1] E. Dogdibegovic, Y. Cheng, F. Shen, R. Wang, B. Hu, J. Power Sources 489 (2021) 229439. https://doi.org/10.1016/j.jpowsour.2020.229439

DOI of original article: 10.1016/j.jpowsour.2018.11.004

Michael C. Tucker

mctucker@lbl.gov