

UC Santa Barbara

UC Santa Barbara Previously Published Works

Title

Seven Basic Tools of Quality Control: The Appropriate Techniques for Solving Quality Problems in the Organizations

Permalink

<https://escholarship.org/uc/item/2kt3x0th>

Author

Neyestani, Behnam

Publication Date

2017-01-03

Seven Basic Tools of Quality Control: The Appropriate Techniques for Solving Quality Problems in the Organizations

Behnam Neyestani

behnam_neyestani@yahoo.com

Abstract: *Dr. Kaoru Ishikawa was first total quality management guru, who has been associated with the development and advocacy of using the seven quality control (QC) tools in the organizations for problem solving and process improvements. Seven old quality control tools are a set of the QC tools that can be used for improving the performance of the production processes, from the first step of producing a product or service to the last stage of production. So, the general purpose of this paper was to introduce these 7 QC tools. This study found that these tools have the significant roles to monitor, obtain, analyze data for detecting and solving the problems of production processes, in order to facilitate the achievement of performance excellence in the organizations.*

Keywords: *Seven QC Tools; Check Sheet; Histogram; Pareto Analysis; Fishbone Diagram; Scatter Diagram; Flowcharts, and Control Charts.*

INTRODUCTION

There are seven basic quality tools, which can assist an organization for problem solving and process improvements. The first guru who proposed seven basic tools was Dr. Kaoru Ishikawa in 1968, by publishing a book entitled "Gemba no QC Shuho" that was concerned managing quality through techniques and practices for Japanese firms. It was intended to be applied for "self-study, training of employees by foremen or in QC reading groups in Japan. It is in this book that the seven basic quality control tools were first proposed. valuable resource when applying the seven basic tools (Omachonu

Neyestani B. (2017, March). "Seven Basic Tools of Quality Control: The Appropriate Quality Techniques for Solving Quality Problems in the Organizations." <https://doi.org/10.5281/zenodo.400832>

and Ross, 2004). These seven basic quality control tools, which introduced by Dr. Ishikawa, are : 1) Check sheets; 2) Graphs (Trend Analysis); 3) Histograms; 4) Pareto charts; 5) Cause-and-effect diagrams; 6) Scatter diagrams; 7) Control charts. Figure 1 indicates the relationships among these seven tools and their utilizations for the identification and analysis of improvement of quality (Kerzner, 2009).




Figure 1: The seven quality control tools (Kerzner, 2009).

Check Sheet

Check sheets are simple forms with certain formats that can aid the user to record data in an firm systematically. Data are “collected and tabulated” on the check sheet to record the frequency of specific events during a data collection period. They prepare a “consistent, effective, and economical approach” that can be applied in the auditing of quality assurance for reviewing and to follow the steps in a particular process. Also, they help the user to arrange the data for the utilization later (Montgomery, 2009; Omachonu and Ross, 2004). The main advantages of check sheets are to be very easily to apply and understand, and it can make a clear picture of the situation and condition of the organization. They are efficient and powerful tools to identify frequently problems, but they dont have effective ability to analyze the quality problem into the workplace. The chech sheets are in several, three major types are such as Defect-location check sheets; tally check sheets, and; defect-cause check sheets (Kerzner, 2009). Figure 2 is depicted a tally

check sheet that can be used for collecting data during production process.

Reason	Day					Total
	Mon	Tues	Wed	Thurs	Fri	
Wrong number						20
Info request						10
Boss						19
Total	12	6	10	8	13	49

Figure 2: Check sheet (Tally) for telephone interruptions

Histogram

Histogram is very useful tool to describe a sense of the frequency distribution of observed values of a variable. It is a type of bar chart that visualizes both attribute and variable data of a product or process, also assists users to show the distribution of data and the amount of variation within a process. It displays the different measures of central tendency (mean, mode, and average). It should be designed properly for those working into the operation process can easily utilize and understand them. Also, a histogram can be applied to investigate and identify the underlying distribution of the variable being explored (Omachonu and Ross, 2004; Forbes and Ahmed, 2011). Figure 3 illustrates a histogram of the frequency of defects in a manufacturing process.




Figure 3: Histogram for variables

Pareto Analysis

It introduced by an Italian economist, named Vilfredo Pareto, who worked with income and other unequal distributions in 19th century, he noticed that 80% of the wealth was owned by only 20% of the population. later, Pareto principle was developed by Juran in 1950. A Pareto chart is a special type of histogram that can easily be apply to find and prioritize quality problems, conditions, or their causes of in the organization (Juran and Godfrey, 1998).. On the other hand, it is a type of bar chart that shows the relative importance of variables, prioritized in descending order from left to right side of the chart. The aim of Pareto chart is to figure out the different kind of “nonconformity” from data figures, maintenance data, repair data, parts scrap rates, or other sources. Also, Pareto chart can generate a mean for investigating concerning quality improvement, and improving efficiency, “material waste, energy conservation, safety issues, cost reductions”, etc., as Figure 4 demonstrated concerning Pareto chart, it can able to improve the production before and after changes (Montgomery, 2009; Kerzner, 2009; Omachonu and Ross, 2004).




Figure 4: Pareto Charts

Fishbone Diagram

Kaoru Ishikawa is considered by many researchers to be the founder and first promoter of the 'Fishbone' diagram (or Cause-and-Effect Diagram) for root cause analysis and the concept of Quality Control (QC) circles. Cause and effect diagram was developed by Dr. Kaoru Ishikawa in 1943. It has also two other names that are Ishikawa diagram and fishbone because the shape of the diagram looks like the skeleton of a fish to identify quality problems based on their degree of importance (Neyestani, 2017). The cause and effect diagram is a problem-solving tool that investigates and analyzes systematically all the potential or real causes that result in a single effect. On the other hand, it is an efficient tool that equips the organization's management to explore for the possible causes of a problem (Juran and Godfrey, 1998). This diagram can provide the problem-solving efforts by "gathering and organizing the possible causes, reaching a common understanding of the problem, exposing gaps in existing knowledge, ranking the most probable causes, and studying each cause" (Omachonu and Ross, 2004). The generic categories of the cause and effect diagram are usually six elements (causes) such as environment, materials, machine, measurement, man, and method, as indicated in Figure 5. Furthermore, "potential causes" can be indicated by arrows entering the main cause arrow (Neyestani, 2017).




Figure 5: The cause and effect diagram (Fishbone Diagram)

Scatter Diagram

Scatter diagram is a powerful tool to draw the distribution of information in two dimensions, which helps to detect and analyze a pattern relationships between two quality and compliance variables (as an independent variable and a dependent variable), and understanding if there is a relationship between them, so what kind of the relationship is (Weak or strong and positive or negative). The shape of the scatter diagram often shows the degree and direction of relationship between two variables, and the correlation may reveal the causes of a problem. Scatter diagrams are very useful in regression modeling (Montgomery, 2009; Oakland, 2003). The scatter diagram can indicate that there is which one of these following correlation between two variables: a) Positive correlation; b) Negative correlation, and c) No correlation, as demonstrated in Figure 6.




Figure 6: Scatter Diagrams

Flowchart

Flowchart presents a diagrammatic picture that indicates a series of symbols to describe the sequence of steps exist in an operation or process. On the other hand, a flowchart visualize a picture including the inputs, activities, decision points, and outputs for using and understanding easily concerning the overall objective through process. This chart as a problem solving tool can apply methodically to detect and analyze the areas or points of process may have had potential problems by “documenting” and explaining

an operation, so it is very useful to find and improve quality into process (Forbes and Ahmed, 2011), as shown in Figure 7.

Test Plan Creation Process




Figure 7: Flow chart of review process

Control Chart

Control chart or Shewhart control chart was introduced and developed by Walter A. Shewhart in the 1920s at the Bell Telephone Laboratories, and is likely the most “technically sophisticated” for quality management (Montgomery, 2009). Control charts is a special form of “run chart that it illustrates the amount and nature of variation in the process over time”. Also, it can draw and describe what has been happening in the process. Therefore, it is very important to apply control chart, because it can observe and monitor process to study process that is in “statistical control” (No problem with quality) accordant to the samplings or samplings are between UCL and LCL (upper control limit (UCL) and the lower control limit (LCL)). “statistical control” is not between UCL and LCL, so it means the process is out of control, then control can be applied to finde causes of quality problem, as shown in Figure 8 that A point is in control and B point is out of control. In

addition, this chart can be utilized for estimating “the parameters” and “reducing the variability” in a process (Omachonu and Ross, 2004). The main aim of control chart is to prevent the defects in process. It is very essential for different businesses and industries, the reason is that unsatisfactory products or services are more costly than spending expenses of prevention by some tools like control charts (Juran and Godfrey, 1998). A Control Chart is presented in the following Figure.




Figure 8: The Shewhart control chart

CONCLUSION

This study identified that it is very essential to apply all seven QC tools for troubleshooting issues within production processes in the organizations. Doubtlessly, all of the aforementioned quality tools should be considered and used by management for identifying and solving quality problems during producing the products and services. Thus, the production processes can be affected and improved by multiple factors of these statistical QC tools. Also, Mirko et al. (2009) designed and developed an effective layout for using these QC in the organizations based on the performance of them, in order to apply appropriately these quality tools for solving quality problems and quality

improvement, as demonstrated in Figure 9. Accordingly, the following Figure interprets how the 7 QC should be employed from first step to end of production processes for identifying the problems of quality performance and controlling them.




Figure 9: An appropriate layout for using 7QC tools with the aim of improving extremely quality performance (Mirko et al., 2009)

References

1. Forbes, L H. & Ahmed S. M. (2011). Modern construction : lean project delivery and integrated practices. Boca Raton, Fly: Taylor and Francis Group.
2. Juran, M., and Godfrey, A. (1998). Juran's quality handbook (5th ed.). Washington, DC: McGraw-Hill Companies, Inc.
3. Kerzner, H. (2009). Project Management: A Systems Approach to Planning,

Neyestani B. (2017, March). "Seven Basic Tools of Quality Control: The Appropriate Quality Techniques for Solving Quality Problems in the Organizations." <https://doi.org/10.5281/zenodo.400832>

- Scheduling, and Controlling (10th ed.). Hoboken, New Jersey: John Wiley & Sons, Inc.
4. Mirko S., Jelena J., Zdravko K., & Aleksandar V. (2009). Basic Quality Tools in Continuous Improvement. *Journal of Mechanical Engineering*, 55(5), pp. 1-9.
 5. Montgomery, D. C. (2009). Introduction to Statistical Quality Control (6th ed.). Danvers, MA: John Wiley & Sons, Inc.
 6. Neyestani B. (2017, February). "Principles and Contributions of Total Quality Mangement (TQM) Gurus on Business Quality Improvement." <https://doi.org/10.5281/zenodo.345428>
 7. Oakland, J. S. (2003). Total Quality Management: text with cases (3rd ed.). Jordan Hill, Oxford, UK: Butterworth-Heinemann, an imprint of Elsevier.
 8. Oberlender, G. D. (2000). Project Management for Engineering and Construction (2nd ed.). New York, USA: McGraw-Hill Companies, Inc.
 9. Omachonu, V. K. & Ross, J. E. (2004). Principles of total quality (3rd ed.). Boca Raton, Florida: Taylor & Francis.