

Lawrence Berkeley National Laboratory

Lawrence Berkeley National Laboratory

Title

Erratum: High power impulse magnetron sputtering: Current-voltage-time characteristics indicate the onset of sustained self-sputtering

Permalink

<https://escholarship.org/uc/item/93r6602s>

Authors

Anders, Andre
Andersson, Joakim
Ehiasarian, Arutjun

Publication Date

2008-05-20

Erratum: High power impulse magnetron sputtering: Current-voltage-time characteristics indicate the onset of sustained self-sputtering

André Anders^{a)}, Joakim Andersson

Lawrence Berkeley National Laboratory, University of California, 1 Cyclotron Road,
Berkeley, California 94720

Arutiun Ehasarian

Materials and Engineering Research Institute, Sheffield Hallam University, Howard St.,
Sheffield S1 1WB, UK

We noticed that Figures 1 and 2 of the original publication showed data of preliminary measurements that are not quite consistent with the text and figure captions.

We regret this mistake and provide here the correct figures.

^{a)}Corresponding author; Electronic mail aanders@lbl.gov




Fig. 1




Fig. 2